

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/8/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 11/5/2012 – 0700, 11/27/2012
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, TX
8. Activity Log			
Time	Major Events		
08:00	<ul style="list-style-type: none"> <li>Internal Command and General Staff meeting</li> </ul>		
10:00	<ul style="list-style-type: none"> <li>Boarded Helicopter</li> <li>Source area, no sheen observed.</li> <li>Frac-Tank City, observed a truck dewatering the pad.</li> <li>MP9.75 LDB observed a RI team.</li> <li>MP10.25 RDB observed an RI team.</li> <li>MP20.75 RDB sheen observed.</li> <li>Observed a sweep boat mobilizing up to the MP21.5 area.</li> <li>Morrow Lake Delta observed a CSD sampling crew.</li> <li>Morrow Lake Delta observed crews removing debris and performing curtain inspections.</li> </ul>		
12:00	<ul style="list-style-type: none"> <li>Arrived at the C0.4 boat launch</li> <li>MP5.25 LDB observed sheen and tar globs.</li> <li>MP5.35 LDB observed sheen and tar globs.</li> <li>MP5.45 LDB observed sheen and tar globs.</li> <li>Sheen and tar globules observed at Ceresco Dam control point.</li> <li>Sheen and tar globules observed collecting with the debris at Ceresco Dam control point.</li> <li>Morrow Lake Delta observed a CSD sampling crew.</li> <li>Morrow Lake Delta observed crews removing debris and performing curtain inspections.</li> <li>Morrow Lake south cove observed a sweep boat operating.</li> <li>Morrow Lake south cove observed sheen and tar globs.</li> </ul>		
16:00	Returned to Boat Launch E4. Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			